

Grundplatte**Fin Strukur**

1	F MAX
2	Z +150
3	F MAX
4	X +11
5	F MAX
6	Y +15
7	F MAX
8	Z +5
9	S 1600
10	M 13
11	F 5
12	Z -2

Fin Kontur

13	LB 1
14	F 5
15	Y +35
16	X +12
17	Y +15
18	X +39
19	Y +35
20	X +38
21	Y +14,5
22	Y +35
23	X +11,5
24	X +17
25	Y +15
26	X +21
27	Y +35
28	X +25
29	Y +15
30	X +29
31	Y +35
32	X +33
33	Y +15
34	X +38
35	Y +20
36	X +12
37	Y +24
38	X +38
39	Y +28
40	X +12
41	Y +32
42	X +38
43	Y +15
44	X +11

Zustellung

45	LB0
46	F 5
47	Z -4
48	Call LB1
49	F 5
50	Z -4,7
51	Call LB1
52	F 5
53	Z +5
54	F MAX
55	Z +150
56	M 30

Düsenplatte

1	F MAX	47	F 5
2	Z +150	48	Z -4
3	F MAX	49	Call LB2
4	X +12,5	50	F 5
5	F MAX	51	Z -6
6	Y+16	52	Call LB2
7	F MAX	53	F 5
8	Z +5	54	Z +5
9	S 1600	55	F MAX
10	M 13	56	Z +150
11	F5	57	M 30
12	Z -2		
13	LB1		
14	F 5		
15	Y +35		
16	X +11		
17	Y +15		
18	X +14		
19	Y +35		
20	X +12,5		
21	Y +16		
22	LB 0		
23	F 5		
24	Z -4		
25	Call LB1		
26	F 5		
27	Z -6		
28	Call LB1		
29	F 5		
30	Z +5		
31	F MAX		
32	X +37,5		
33	F MAX		
34	Y +16		
35	Z -2		
36	LB 2		
37	Y +35		
38	X +36		
39	Y +15		
40	X +39		
41	Y +35		
42	X +16		
43	LB 3		
44	F 5		
45	Z -4		
46	Call LB2		

Deckel

1	F MAX		
2	Z +150		
3	F MAX	49	F 10
4	Y +13,5	50	Z +5
5	F MAX	51	Call LB1
6	X +25	52	F MAX
7	F MAX	53	Z +150
8	Z +5	54	M 30
9	S 1600		
10	M 13		
11	F 10		
12	Z -2		
13	LB 1		
14	F 5		
15	X +12,5		
16	Y +35		
17	X +14		
18	Y +15		
19	X +29		
20	Y +9		
21	X +21		
22	Y +12		
23	X +11		
24	Y +35		
25	X +13		
26	Y +13,5		
27	X +37,5		
28	Y +35		
29	X +39		
30	Y +12		
31	X +29		
32	Y +15		
33	X +36		
34	Y +35		
35	X +38		
36	Y +34		
37	F 20		
38	Z +2		
39	F MAX		
40	Y +13,5		
41	F MAX		
42	X +25		
43	F MAX		
44	Z 0		
45	LB 0		
46	F 10		
47	Z +4		
48	Call LB1		

Alle Platten**O-Ring Nut**

1	F MAX
2	Z +150
3	F MAX
4	X -9
5	F MAX
6	Y +5
7	F MAX
8	Z +5
9	S 1600
10	F5
11	M 13
12	Z -1,5
13	Y +9
14	X -5
15	Y +41
16	X -9
17	Y +45
18	X -41
19	Y +41
20	X -45
21	Y +9
22	X -41
23	Y +5
24	X -9
25	Z +5
26	F MAX
27	Z +150
28	M 30

Tabelle1

Tabelle1